




UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION IV

ENVIRONMENTAL SERVICES DIVISION
ATHENS, GEORGIA 30613



MEMORANDUM

DATE: July 29, 1991

SUBJECT: Carrier Air Conditioning Site, Collierville, TN,
Remedial Investigation Report

FROM: Pat Stamp *Pat Stamp*
Laboratory Quality Assurance Specialist
Laboratory Evaluation & Quality Assurance Section

TO: Beth Brown, Remedial Project Manager
North Superfund Remedial Branch
Waste Management Division

THRU: Wade Knight, Chief *WK*
Laboratory Evaluation & Quality Assurance Section

We have reviewed the subject document and have the following comments:

- ✓ 1. Table of Contents -- Everything from Section 6.0 to the end needs to be corrected.
- ✓ 2. Data qualifiers should be explained at the end of each table.
- ✓ 3. Page 52, Phase III -- This paragraph begins with the statement that "...groundwater samples were collected from all monitoring wells." In the same paragraph another sentence states "[s]hallow wells had insufficient recharge for sampling." This needs to be clarified.
- ✓ 4. Page 73, External QC
 - ✓ ~~4~~ a. There are no results from sample #B49-11 in Appendix B. ~~missing are B37-7, B37-8.~~
 - ✓ b. There are no results form sample #s 08159002, 0815902A or 08159102B on page H-21 or any other page in Appendix H.
- ✓ 5. Page 85, Paragraph 1 -- Table 4-13 shows results from lead and zinc analyses from the May 16, 1990, sampling. The data tables on pages H-23-25 show results from only volatile organic compounds instead of "full data tables" from the November 13-17, 1990, sampling. There does not appear to be any correlation between these sampling events or between the results.



10663325